

June 20, 1979

Wm. Harman
1826 W. Latoka St.
Springfield, MO 65807

Dear Mr. Harman:

On a recent occasion, surveillance and enforcement personnel from this office investigated a complaint and found that a substance resembling crank case oil had apparently been drained or discharged in front of your property. This office has no way of knowing who might be responsible.

Let me advise you that if this spillage is due to any activities on your part, this constitutes violations of City, State, and Federal laws. The laws contain severe penalties for the discharge of oil or petroleum products. This office maintains periodic surveillance throughout the corporate limits of the City, and will watch this area closely. If the discharge described is not due to any activity on your part, you can help significantly by reporting any such activities immediately to this office.

Yours truly,

J.D. Slaughter
Water Pollution Control Inspector II
Surveillance and Enforcement

JDS:js

cc: John R. Nixon, Department of Natural Resources
Robert Schaefer, P.E., Superintendent of Sanitary Services

1826 W. LATOKA